

From: Sarah Fields <sarah@uraniumwatch.org>
To: Paul Baker <paulbaker@utah.gov>
Date: 7/8/2010 3:52 PM
Subject: Photos of Pandora Vent #5.
Attachments: Pandora_vent5.7-3-10.001.JPG; Pandora_vent5.7-3-10.002.JPG; Part.003

CC: Tom Munson <tommunson@utah.gov>
Dear Mr. Baker,

Attached are photos of Pandora Vent #5. Although I thought it was not operating, the annual 40 CFR Part 61, Subpart B, compliance report submitted to the Div. of Air Quality and EPA in March 2009 shows that it was operating in 2009.

Vent #5 is in the location of Unnamed 7' Vent (road south from vent leads to SnowBall mine). There is a vent to the SW of this vent on the Denison Mines 12-09 map, shown as Pandora #5 Vent Hole. However, on the ground, the writing on the vent is SB 2 (3000-3-36-28-24). Unclear is this is the Vent #5 referred to in the annual report. There are other discrepancies in vent numbers on Denison maps.

You can see part of the grate in the front, the rest of the grate is also off the vent, on the other side of the vent.

I also sent the pictures to the BLM.

Sarah Fields



